

Belzona Furniture Repair

ID: 8482

Industry: *Building & Structures*
Application: *ENC-Engines and Casings*
Substrate: *Chipboard*
Products: *Belzona® 1212*

Customer Location: *Slovakia*
Application Date: *2019*

Problem

The user needed to use this wardrobe immediately, without any dismantling, with repair for a long time.



Photograph Descriptions

1. Ripped out door hinge
2. Belzona® 1212 application
3. Installation in short time
4. Ready to use

Application Situation

After long time using was the wardrobe door hinge ripped out.

Application Method

Application was carried out using adapted Instructions for use.

Belzona Facts

User knows Belzona products from industry using. He needed quick, good and long-standing repair. Belzona® 1212 was his genuine solution.

For more examples of Belzona Know - How In Action, please visit: <https://khia.belzona.com>

ISO 9001:2015
Q.09335
ISO 14001:2015
EMS 509612

Belzona products are
manufactured under an ISO
9001 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve