

Pump Repair with Belzona

ID: 7604

Industry: *Fluid Flow*
Application: *CEP-Centrifugal Pumps*
Substrate: *Stainless Steel*
Products: *Belzona® 1311 (Ceramic R-Metal)*
Belzona® 1391 (HT)

Customer Location: *Cellulose production plant, Slovakia*
Application Date: *2010*

Problem

Corrosion and erosion from chemicals (caustification plus CaCO_3 a CaO).



Photograph Descriptions

1. Damaged pump
2. After blasting
3. Belzona® 1311 application
4. Belzona® 1391 application

Application Situation

Pump erosion and corrosion every 6 months.

Application Method

Application was carried out in accordance with Instructions for use.

Belzona Facts

To weld it is very expensive and it takes a lot of time, also lifetime of the welding is much more shorter by comparison with welding.

For more examples of Belzona Know - How In Action, please visit: <https://khia.belzona.com>

ISO 9001:2015
Q.09335
ISO 14001:2015
EMS 509612

Belzona products are
manufactured under an ISO
9001 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve