

# Belzona Keeps Vehicles Moving

ID: 1055

Industry: *General Industry*

Customer Location: *Vehicle testing station Bratislava, Slovakia*

Application: *FPA-Floor Problem Areas*

Application Date: *2006*

Substrate: *Floor tiles*

Products: *Belzona® 5811 (Immersion Grade)*  
*Belzona® 9211 (Supergrip aggregate)*

## Problem

*During the rain or snow, vehicles were slipping when moving off the brake testing rollers.*



## Photograph Descriptions

1. Vehicle testing station
2. Vehicle during the brake testing
3. 2 years in service

## Application Situation

Application of grip system to provide better traction on the workshop floor.

## Application Method

Application was carried out in accordance with Instructions for use. Belzona® 5811 was applied by brush in a diagonal stripe pattern and blinded with Belzona® 9211.

## Belzona Facts

Customer was looking for quick and “clean” solution. The Belzona solution provided an effective grip system as well as chemical resistance to any spillage or leaks that may occur. The system has proven itself in service.

For more examples of Belzona Know - How In Action, please visit: <https://khia.belzona.com>

ISO 9001:2015  
Q.09335  
ISO 14001:2015  
EMS 509612

Belzona products are  
manufactured under an ISO  
9001 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

