

Belzona Improves Conveyer Efficiency

ID: 1067

Industry: General Industry
Application: SHM-Solids Handling Machinery
Substrate: Rubber
Products: Belzona® 2211 (MP Hi-Build Elastomer)

Customer Location: Automotive company, Slovakia
Application Date: 2006

Problem

Products were sliding on the belt due to incline and smooth surface.



Photograph Descriptions

1. Slippery belt
2. Application of Belzona® 2211
3. Steel plates for moulding Elastomer to shape
4. Completed belt ready to work

Application Situation

Elevated conveyer system.

Application Method

Application was carried out in accordance with Instructions for use.

Belzona Facts

Customer had problems with sliding of products. To change the belt was expensive. Creating cleats/treads with Belzona was quick, cheap and effective solution.

For more examples of Belzona Know - How In Action, please visit: <https://khia.belzona.com>

ISO 9001:2015
Q.09335
ISO 14001:2015
EMS 509612

Belzona products are
manufactured under an ISO
9001 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve