

Belzona Stops Floor Drain Leaks

ID: 2458

Industry: General Industry
Application: FPA-Floor Problem Areas
Substrate: Stainless Steel, Concrete, Ceramic tiles
Products: Belzona® 4111 (Magma Quartz)

Customer Location: Machinery manufacturer, Slovakia
Application Date: 2008

Problem

Leakage from the floor drains was problem from the start. Connection between steel and tiles was faulty. Result was the leakage to the next floor.



Photograph Descriptions

1. Situation before repair
2. Situation at the floor below
3. Surface preparation being carried out
4. Belzona® 4111 in place creating a watertight seal

Application Situation

Drain in kitchen floor.

Application Method

Application was carried out in accordance with Instructions for use.

Belzona Facts

Customer had tried several alternatives to repair the drain but none worked. Repair with Belzona® 4111 ensured necessary water tightness due to excellent adhesion to different substrates and non-shrink properties.

For more examples of Belzona Know - How In Action, please visit: <https://khia.belzona.com>

ISO 9001:2015
Q.09335
ISO 14001:2015
EMS 509612

Belzona products are
manufactured under an ISO
9001 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve