

# Chemical Canalization Entry Repaired with Belzona

ID: 7617

Industry: *Chemical & Petrochemical*  
Application: *TCC-Tanks and Chemical Containment Areas*  
Substrate: *Concrete / Steel*  
Products: *Belzona® 4131 (Magma-Screed),  
Belzona® 5811 (Immersion Grade)*

Customer Location: *Petrochemical company,  
Slovakia*  
Application Date: *2016*

## Problem

*Corrosion of the steel frame and damage to the concrete*



## Photograph Descriptions

1. Chemical canalization entry
2. Belzona Conditioner application
3. Belzona® 4131 application
4. Belzona® 5811 in 2 layers

## Application Situation

The concrete was destroyed from chemicals.

## Application Method

Application was carried out in accordance with Instructions for use.

## Belzona Facts

Main benefit for the customer was time, because all repair was carried in very short time, but also important is resistant against chemicals.

For more examples of Belzona Know - How In Action, please visit: <https://khia.belzona.com>

ISO 9001:2015  
Q.09335  
ISO 14001:2015  
EMS 509612

Belzona products are  
manufactured under an ISO  
9001 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

