

Belzona Protects Francis Turbine Runner

ID: 7591

Industry: *Power*
Application: *CEP-Centrifugal Pumps*
Substrate: *Steel*
Products: *Belzona® 1311 (Ceramic R-Metal),
Belzona® 1341 (Supermetalgilde)*

Customer Location: *Electricity producer, Slovakia*
Application Date: *2014*

Problem

Erosion/Corrosion



Photograph Descriptions

1. Turbine in very bad condition
2. Repair in progress
3. Repair in progress
4. Turbine like new

Application Situation

Francis Turbine Runner was suffered extensive damage.

Application Method

Application was carried out in accordance with Instructions for use.

Belzona Facts

This was not first Belzona protection of Francis turbine runner for this customer. The client was so pleased with performance of the previous repair they ordered this repair and for another turbine.

For more examples of Belzona Know - How In Action, please visit: <https://khia.belzona.com>

ISO 9001:2015
Q.09335
ISO 14001:2015
EMS 509612

Belzona products are
manufactured under an ISO
9001 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve