

Belzona Protects River Back-Flow Valves

ID: 7563

Industry: Water / Wastewater
Application: VPF-Valves, Pipes and Fittings
Substrate: Iron
Products: Belzona® 1111 (Super Metal),
Belzona® 5811 (Immersion Grade),
Belzona® 2211 (MP Fluid Elastomer)

Customer Location: Water management company,
Slovakia
Application Date: 2011

Problem

The valves suffered from erosion and corrosion through continued use. The valve was so badly damaged that it leaked even when shut.



Photograph Descriptions

1. Leaking back-flow valve before reconstruction
2. Valve after blasting
3. Shut off flap coated with Belzona® 5811 and Belzona® 2211
4. Valve back in operation

Application Situation

River backflow valves at a water treatment plant.

Application Method

Application was carried out in accordance with Instructions for use.

Belzona Facts

A Belzona repair avoiding costly repairs or replacement. This repair got the valve back in operation faster than traditional methods and with minimal disruption to the plant operation.

For more examples of Belzona Know - How In Action, please visit: <https://khia.belzona.com>

ISO 9001:2015
Q.09335
ISO 14001:2015
EMS 509612

Belzona products are
manufactured under an ISO
9001 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve