

Cyclone Coating Protection with Belzona

ID: 7611

Industry: *Food & Drink*
Application: *SHM-Solids Handling Machinery*
Substrate: *Steel*
Products: *Belzona® 1812 (Ceramic Carbide FP)*

Customer Location: *Starch factory, Slovakia,*
Application Date: *2011*

Problem

Damaged cyclone



Photograph Descriptions

1. Ready for repair
2. Belzona® 1812 application
3. Belzona® 1812 application detail

Application Situation

Milled corn material suffers and also adheres on the cyclone surface.

Application Method

Application was carried out in accordance with Instructions for use.

Belzona Facts

Conventional welding to be out of service too long and also it is not long-lasting solution.

For more examples of Belzona Know - How In Action, please visit: <https://khia.belzona.com>

ISO 9001:2015
Q 09335
ISO 14001:2015
EMS 509612

Belzona products are
manufactured under an ISO
9001 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve