

Belzona Pump Seating Repair

ID: 7600

Industry: *Steel & Metal Processing*
Application: *CEP-Centrifugal Pumps*
Substrate: *Iron casting*
Products: *Belzona® 1111 (Super Metal)*

Customer Location: *Metallurgic plant, Slovakia*
Application Date: *2014*

Problem

Corrosion, mechanical damage



Photograph Descriptions

1. Damaged pump seating
2. Machining of the Belzona® 1111
3. Ready for customer

Application Situation

After long time operation the pump has worn down seating. Result is a big clearance of the bearing.

Application Method

Application was carried out in accordance with Instructions for use.

Belzona Facts

Welding of the seating is very difficult, takes a long time. Belzona solution means very good repair and result is that customer uses this Belzona repair also for another pumps.

For more examples of Belzona Know - How In Action, please visit: <https://khia.belzona.com>

ISO 9001:2015
Q.09335
ISO 14001:2015
EMS 509612

Belzona products are
manufactured under an ISO
9001 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve