

Slide Assembly with Belzona Repair

ID: 7606

Industry: *Steel & Metal Processing*

Customer Location: *Metallurgic producer, Slovakia*

Application: *ENC-Engines and Casings*

Application Date: *2014*

Substrate: *Steel*

Products: *Belzona® 1311 (Ceramic R-Metal)*

Problem

Corrosion accelerated due to the inclusion of water and chemicals within the process



Photograph Descriptions

1. Damaged slide assembly
2. Belzona® 1311 application
3. All surface were sanded down
4. Support ready to work

Application Situation

Slide assembly were damaged from corrosion.

Application Method

Application was carried out in accordance with Instructions for use.

Belzona Facts

Belzona was chosen because welding takes very long time with risk of the compromising the structural integrity.

For more examples of Belzona Know - How In Action, please visit: <https://khia.belzona.com>

ISO 9001:2015
Q.09335
ISO 14001:2015
EMS 509612

Belzona products are
manufactured under an ISO
9001 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve