

Belzona Repairs a Car Engine Casing

ID: 7567

Industry: *Transport*
Application: *ENC-Engines and Casings*
Substrate: *Iron*
Products: *Belzona® 1111 (Super Metal)*

Customer Location: *Civil Society, Slovakia*
Application Date: *2016*

Problem

The freezing winter temperatures had caused excessive movement and a crack in the engine casing.



Photograph Descriptions

1. Cracked engine
2. Crack detection
3. Surface preparation
4. Belzona® 1111 application with reinforcement tape

Application Situation

Cracked Engine Casing on a government vehicle.

Application Method

Application was carried out in accordance with Instructions for use.

Belzona Facts

Welding this kind of damage would take a lot of time and money. Rebuilding with Belzona® 1111 was a faster and more economical solution for the customer.

For more examples of Belzona Know - How In Action, please visit: <https://khia.belzona.com>

ISO 9001:2015
Q.09335
ISO 14001:2015
EMS 509612

Belzona products are
manufactured under an ISO
9001 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve