

# Belzona Refurbishes Brake Test Rollers

ID: 7609

Industry: *Transport*  
Application: *SHM-Solids Handling Machinery*  
Substrate: *Steel*  
Products: *Belzona® 1821 (Fluid Metal)*

Customer Location: *Vehicle testing station, Slovakia*  
Application Date: *2016*

## Problem

*After many thousand tests the surface of the rollers required a new non-slip surface applying.*



## Photograph Descriptions

1. Damaged rollers
2. Belzona® 9211 Supergrip Aggregate application into Belzona® 1821
3. Ready to work

## Application Situation

Brake test rollers at vehicle testing station.

## Application Method

Application was carried out in accordance with Instructions for use.

## Belzona Facts

Customer needed quick repair in good quality and Belzona grip system has a proven track record for this application.

For more examples of Belzona Know - How In Action, please visit: <https://khia.belzona.com>

ISO 9001:2015  
Q 09335  
ISO 14001:2015  
EMS 509612

Belzona products are  
manufactured under an ISO  
9001 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

